

Siemens VDO Trading GmbH  
 Heinrich-Hertz-Str. 45  
 D-78052 Villingen-Schwenningen  
<http://www.siemensvdo.com>

**For internal use only!**  
**Technical alterations are subject to change without notice**

To: Technical managers / Service technicians	Date: October 16, 2006
Inland <input checked="" type="checkbox"/> NSO / ND <input type="checkbox"/> RS / EWR <input type="checkbox"/> IS / EW, ISE / EWEI <input type="checkbox"/> For info: NSO / ND	from: Mr Armleder Dept.: SV S SO VIL SP TCO PS
Abroad <input checked="" type="checkbox"/> NSO / ND	Phone: 07721 / 67 2442
Product / System: DTCO	Fax: 07721 / 67 2917
Belonging to: <b>Retrofitting</b>	Email: dieter.armleder@siemens.com
<b>SI No.: 116 039</b>	Page: 1 of 2

**SI No. 116 011 is no longer valid and is being replaced by SI No. 116 039.**

**Installation Suggestion for: FORD TRANSIT Rear-wheel Drive**

	Vehicle Data		TRANSIT Rear-wheel Drive		
	Year of manufacture		starting 2006		
	Vehicle type		2,4   TDCI	2,3   DOHC 16 V	
	Power (HP)		100 /115/140	145	

Required Components	Part Number
DTCO	1381-0070300001 Illumination green, dimming A 2, w/o CAN
DTCO	1381-0061200001 Illumination green, dimming A 2, w/o CAN D1+D2
KITAS for five-speed gears	2171-20002100
KITAS für six-speed gears	2171-50102400
KITAS cable	2170-80210420
Connecting cable connector A	1318-90100000
Mounting frame	1324-90010500

In addition the following Ford parts must be purchased for vehicles without a second radio compartment:		
Quantity	Description	Ford Part Number
1	Installation console	144 82 51
1	Cover	101 29 07
2	Cover plug	143 10 90
2	Sheet metal screws	406 76 32
2	Sheet spring nut	404 61 14

### KITAS Installation



- Remove blind plug
- Install KITAS:
  - for 5-speed gears KITAS 2171-20002100
  - for 6-speed gears KITAS 2171-50102400

### DTCO Installation



To be installed in the radio compartment on the left-hand side

**Time required for installation:**

Approx. 2 hours